

### **ABSTRACT**

A method of surface treatment of friction members includes providing a friction member made of PMMC material. A transfer layer is formed on the active surface of the friction member by removing the top layer of the matrix material to expose a surface with the embedded reinforcing particles.